Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1	"10791070"	US-PGPUB; USPAT	AND	ON	2007/08/15 18:11
L2	1290	plurality & sensor & monitoring & process\$4 & signal & (electrostatic with discharge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2007/08/15 18:11
L3	63	"324"/\$.ccls. & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:12
L4	29	"324"/457 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND .	OFF	2007/08/15 18:28
L5	12	"250"/\$.ccls. & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:14
L6		"250"/324 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:13
L7	21	"340"/\$.ccls. & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:14
L8	2	"340"/649 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:14

L9	1	"600"/\$.ccls. & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:15
L10	0	"600"/513 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:15
L11	1	"700"/\$.ccls. & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:16
L12	0	"600"/300 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:15
L13	1	"700"/108 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:15
L14	. 2	"702"/\$.ccls. & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L15	1	"702"/33 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L16	0	"702"/38 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17

L17	1	"702"/58 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L18	0	"702"/60 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L19	0	"702"/118 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L20	0	"702"/120 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L21	0	"702"/187 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:17
L22	4	"324"/403 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:28
L23	8	"324"/414 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:28
L24	0	"324"/404 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:29

1 1	"324"/405 & (electrostatic with (field with sensor)) & discharge	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	AND	OFF	2007/08/15 18:29
-----	--	---	-----	-----	------------------

8/15/2007 6:29:12 PM C:\Documents and Settings\fsuarez\My Documents\EAST\Workspaces\081304\_10791070.wsp